HAZARD RANKING SYSTEM (HRS) DOCUMENTATION RECORD - REVIEW COVER SHEET

Name of Site: Jackpile-Paguate Uranium Mine

EPA ID No.: NMN000607033

Contact Persons

Site Investigation: Brenda Nixon Cook, NPL Coordinator, EPA Reg.6 (214) 665-7436


(Name) (Telephone)


Documentation Record: Brenda Nixon Cook, NPL Coordinator, EPA Reg.6 (214) 665-7436


(Name) (Telephone)


Pathways, Components, or Threats Not Scored

- Ground Water Pathway: The ground water migration pathway has not been scored because although there is analytical data to support a release, there is not a sufficient number of targets to impact the site score. Based on information available at this time, evaluation of the ground water migration pathway would not affect the listing decision.
- Ground Water to Surface Water Pathway: The ground water to surface water pathway has not been scored because although ground water in the Jackpile Sandstone interchanges with water in the Rio Moquino and Rio Paguate through unconsolidated alluvium deposits along the stream channels, the overland flow component score was sufficient for site listing.
- 3) Soil Exposure Pathway: The soil exposure pathway has not been scored. Based on information available at this time, evaluation of the soil exposure pathway would not affect the listing decision.
- 4) Air Pathway: The air migration pathway has not been scored. Based on information available at this time, evaluation of the air migration pathway would not affect the listing decision.
- 5) Surface Water Pathway: The drinking water and environmental threats have not been scored. Based on information available at this time, evaluation of the drinking water and environmental threats would not affect the listing decision.









HRS DOCUMENTATION RECORD - REVIEW COVER SHEET

Site Name: Keddy Mill

EPA ID No.: MEN000106078

Contact Persons

Site Investigation: H&S/Nobis Environmental JV LLC. (HSNE)

Superfund Technical Assessment and Response Team III (START)

160 East Main Street, Suite 2F Westborough, Massachusetts 01581

(508) 366-7442

(Mr. Denis McGrath, CHMM - (978) 703-6016)

Documentation Record: HSNE

START

160 East Main Street, Suite 2F Westborough, Massachusetts 01581

(508) 366-7442

(Mr. Denis McGrath, CHMM - (978) 703-6016)

Site Contact: U.S. Environmental Protection Agency (EPA) Region 1

5 Post Office Square, Suite 100 Boston, Massachusetts 02109-3912

(617) 918-1407

(Ms. Martha Bosworth)

Pathways, Components, or Threats Not Scored

The ground water, drinking water threat of the surface water, soil exposure, and air migration pathways were not scored in this Hazard Ranking System (HRS) documentation record because the human food chain and environmental threats of the surface water migration pathway are sufficient to qualify the Keddy Mill for the National Priorities List (NPL).

Ground Water Migration Pathway

Based upon the location and proximity of the surrounding drinking water supply resources, no nearby drinking water supplies are known or suspected to have been impacted by a release from sources; therefore, this pathway has not been included in this HRS documentation record [Ref. 3].

Soil Exposure Pathway

Soil sampling has been limited to the Keddy Mill property itself [Ref. 4, pp 23-34; Ref. 6, p. 19]. Based upon the lack of a resident population, terrestrial sensitive environments, and the relatively low nearby population targets, the resulting pathway score would not contribute significantly to the overall site score. This pathway has not been included in this HRS documentation record.


Air Migration Pathway

To date, a release of hazardous substances to air from on-site sources has not been documented; consequently, the resulting pathway score would not contribute significantly to the overall site score. This pathway has not been included in this HRS documentation record.

Keddy Mill MEN000106078

Keddy Mill MEN000106078

Keddy Mill MEN000106078



HAZARD RANKING SYSTEM (HRS) DOCUMENTATION RECORD - REVIEW COVER SHEET

Name of Site: MacMillan Ring Free Oil

EPA ID No.: ARD008049207

Contact Persons

Site Investigation: Brenda Nixon Cook, NPL Coordinator, EPA Reg.6 (214) 665-7436

> (Telephone) (Name)

Documentation Record: Brenda Nixon Cook, NPL Coordinator, EPA Reg.6 (214) 665-7436

> (Telephone) (Name)

Pathways, Components, or Threats Not Scored

Although the surface water migration pathway score is sufficient to list the site, contamination in other media has been identified that may pose a threat to human health and the environment and may be evaluated in the future (Ref. 5).

- 1) Ground Water Pathway: The ground water migration pathway has not been scored because, based on information available at this time, scoring of the ground water migration pathway would not significantly affect the listing decision (Ref. 1, Sec. 2.2.3).
- 2) Soil Exposure Pathway: The soil exposure pathway has not been scored. Based on information available at this time, evaluation of the soil exposure pathway would not affect the listing decision (Ref. 1, Sec. 2.2.3).
- 3) Air Pathway: The air migration pathway has not been scored. Based on information available at this time, evaluation of the air migration pathway would not affect the listing decision (Ref. 1, Sec. 2.2.3).
- 4) Surface Water Pathway: The Surface Water Pathway has been scored for the Human Food Chain Threat and Environmental Threat. The drinking water threat has not been scored. Based on information available at this time, evaluation of the drinking water threat would not affect the listing decision (Ref. 1, Sec. 2.2.3).

